


Tone Burst CS520 Latency Measurements


Relevance: Working Morse Code With Long Latency Is difficult. This Test Was Made to Characterize The Delay Time.

TONE BURST INPUT TO CS520

CS520 HEADSET BURST OUTPUT



25 mS



15 mS

Results: Envelope Audio Latency 15 to 25 mS